

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Agency, REGION 1</th></have<>	County: Agency, REGION 1	
1	7.80		T	Г	$\overline{\Box}$	minimums been met for	Washington	
2	7.80				+		ENTRY POINT	
3	7.80		<del>                                     </del>		++	this day?	EP-A	
4	7.80				$\forall \exists$		PWS ID 4100898	
5	7.80				$\dagger$	TIMBER WATER ASSOCIATION		
6	7.80				$\forall$			
7	7.80				$\forall$	Sample period: October · 2024		
8	7.80				$\forall$			
9	7.80				77	. Month/Year		
10	7.80				$\sqcap$	Number of excursions during this month:  (Over 9 excursions in 6 months is a violation.  Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.  Reference  Minimum Water Quality Parameter(s) as set by State:  pH 7.2  Print Name: Taba a Heid Signature:		
11	7.80				$\forall$			
12	7.80				$\Box$			
13	A CONTRACTOR OF THE PARTY OF TH	ER	00	TAG	-			
14	7.80							
15	7.80							
16	7.80							
17	7.80		ļ		Ш			
18	7.80		ļ		$\perp \perp$			
19	7.80		<u> </u>		$\bot$			
20	7.80				$\bot$			
21	7.80	ļ	ļ		$\coprod$			
22	7.80				$\Box$			
23	7-80				H			
24	7-80		<b> </b>					
25			<del> </del>	<u> </u>	H			
26	<u> </u>		<u> </u>	<b>  </b>	H			
27					H			
28			ļ		H			
30	120	21/5	1 -	01700	H			
		OKE	-	PIPE	H	Send to DWP within 10 days after end of		
31	PLA		discussion of the last of the	DOWN	H	sampling period		
(No = N = Excursion) Total N's								

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/