

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	<>Have County: Agency: REGION 1	County: Agency: REGION 1 Washington	
1	7.80				N	minimums	ENTRY POINT	
2	7.80					been met for this day?		
3	7.80	-				tilis day :	EP-A	
4	7.80				$\prod$	PWS ID 4100898 TIMBER WATER ASSOCIATION		
5	7.80							
6	7.80							
7	7.80					Sample period:		
8	7.80							
9	7.80							
10	7.80					Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
11	7.80							
12	7.80							
13	7.80							
14	7.80							
15	7.80							
16	7.80	)			Andrew Control			
17	7.80				-	Reference		
18	780				-	7.5.		
19	7.80						Minimum Water Quality	
20	7.80				and of the same	Parameter(s) as set by State:		
21	7.80				The state of the s			
22	7.80				Transmitted Broads	PIT T.Z		
23	7.80				Marine and a second			
24	7.80	)			and the second second			
25	7.80							
26	7.80							
27	7.80					Print	Name: Tabata Heidt	
28	7.80				payment these		ature: Jerof	
29	7.80				Act of the last of		& Phone#: 07-02-25	
30	7.80					1		
31						1	I to DWP within 10 days after end of bling period	
(No = N = Excursion) Total N's								

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/