

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	pН	Alk	RAWI	FINISH	Y/N	< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1	
1_						minimums been met for	ENTRY POINT	
2						this day?	EP-A	
3							PWS ID 4100922	
4						VERNONIA, CITY OF		
5				1-7	1/			
6	7.3		31	61	1	Sample period: Jan 2021 Month/Year		
7			-					
8								
9								
10							Something the second section of the section of th	
11						Number of excursions during this month: (Over 9 excursions in 6 months is a violation.		
12								
13						Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
14								
15								
16						Set by the State.		
17								
18						Reference		
19			00		./			
20	7.4		33	65	<u> </u>		Minimum Water Quality	
21						8-	Parameter(s) set for this PWS:	
22	y it give						pH 7.3	
23								
24								
25								
26	,							
27							-00 00 1	
28						Print Name: Set 5000000000000000000000000000000000000		
29								
.30								
31						7		
(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350