

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	LRAW	Finish	AN	< <have< th=""><th>County: Columbia</th><th>Agency: REGION 1</th></have<>	County: Columbia	Agency: REGION 1	
1		-				minimums been met for	ENTRY	POINT	
2						this day?	EP-	, . A	
3									
4	-						PWS ID 41	00922	
5						-	VERNONIA, C	ITY OF	
6									
7						Sample no	riod: June /	2021	
8				and some things		Sample pe		Month/Year	
9	7.4		29.9	43:5	4		**	nontri i odi	
10	,								
11						Number of	excursions duri	ng this month: \mathcal{L}	
12						(Over 9 exc	ursions in 6 mont	hs is a violation.	
13							and Distribution e		
14		poudandouskeuska Phil				cumulative).	. An 'excursion' is	s any day in which the	
15					.,	water quality set by the S		Il below the minimum	
16	7.4		25,9	28,8	F	set by the o	iaic.		
17									
18						Refe	rence ———		
19						_	mg 0: 58 <i>8</i> .0	100	
20							/inimum Water (Parameter(s) set		
21							arameter(2) ser	IOI THIS LAND.	
22	7.34						pH 7.3		
23									
24	***************************************				Puber that the CONTRACTOR				
25									
26 27	-		***************************************		***************************************				
28						Print Nan	ne Tell (Buch	
29				·		Signature: Allh Soll			
.30						Date: 7			
31						Date: <u>/ ~</u>	1-41	-	
(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling per									

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350