

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	pН	Alk	<b>LRAW</b>	Finish	Y/N	< <have< th=""><th>County: Columbia</th><th>Agency: REGION 1</th></have<>	County: Columbia	Agency: REGION 1	
						minimums	ENTRY		
1					ederación (Principal Company)	been met for		,	
3						this day?	EP	A	
4							PWS ID 4	100922	
5							VERNONIA,		
6	7.4		49.4	30.5		Ę.	A STATE ACT ATT THE		
7	1.7		1101	5000			<b>~</b> 1 1		
8						Sample period: October 2021			
9				·				Month/Year	
10							namen and the second section of the secti		
11						Number of excursions during this month:			
12						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
13	· · · · · · · · · · · · · · · · · · ·								
14		****							
15				•	<del>anderlistik pelijudski</del>				
16									
17		almada en carrendo en consenten			edy area (20 and 10				
18						Reference			
19									
20						N	Ainimum Water	Quality	
21	*					.F	Parameter(s) se	t for this PWS:	
22	7 / p.24						pH 7.3		
23						-			
24					·				
25									
26	,								
27	73	,	42.3	35,9			0.0	0 1	
28						Print Nan	ne: Jell	Surch	
29						Signature: /// &//			
.30						Date: _//	1-8-21		
31						Date	and the second s	doperate	
(No =	(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350