

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	LRAW	Finish	Y/N	< <have< th=""><th>County: Columbia</th><th>Agency: REGION 1</th></have<>	County: Columbia	Agency: REGION 1
1						minimums been met for	ENTRY	POINT
2						this day?	EP	. A
3					_ 1			
4	7.3		29.9	4B3	4		PWS ID 4	100922
5							VERNONIA,	CITY OF
6								
7						Sample n	eriod: June	2027
8						Month/Year		
9	nakan makala ke kemanan dapar dakan dapar dakan dapar dapar dakan dapar dapar dapar dapar dapar dapar dapar da							
10							· · · · · · · · · · · · · · · · · · ·	
11						Number of	excursions dur	ing this month: $\underline{\emptyset}$
12						1		ths is a violation.
13							and Distribution	
14		266				cumulative). An 'excursion' i	is any day in which the all below the minimum
15	7.4	23.9	28.8		Y	set by the		
16						00.090	2 0 0 0 0 0 1	
17					allo d'anno con l'agric	_		
18						Ref	erence ———	
19								Occaliba
20	,						Minimum Water Parameter(s) se	
22	7 . g.24							
23		31.3	51.2	. , ,	Y		pH 7.3	
24								
25	aldren i North and Consideration (1990)							
26	*							
27	ACTION OF THE PARTY OF THE PART				,			
28	7.4	20.4	29.9		Y	Print Na	me: Tell	Buch
29					1	Signatu	// // \	And the state of t
.30						Date:	6-27	
31						Date	<u> </u>	9000 11

(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350