

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1			en i dan danaga in careno	para la Paris Sina de Carrer	es Arcane problements
2					
2 3 4					
4	7.3	25.2			V,
5					-
6					
7					
8					
9					
10					
11	7.5	37.7			Y
12					
13					
14					
15					
16					
17					
18	7.4	46.7			Y
19					1
20					
21					
22					
23					
24					
25	7.3	33.9			Y
26					
27					
28					
29					
30					
31					
No = N	1 = Exc	ursion	Total	l N's	4

< <have< th=""><th>County: Columbia Agency: REGION 1 ENTRY POINT</th></have<>	County: Columbia Agency: REGION 1 ENTRY POINT			
been met for this day?	EP-A			
PWS ID 4100922 VERNONIA, CITY OF				

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Number of excursions during this month: otin 4

Minimum Water Quality Parameter(s) as set by State:	
pH 7.3 Alk 20.0 (Alkalinity)	
Print Name: Jelf Buch	
Signature: Mh &M	_
Date & Phone#: 11-8-23 429-6921	_
Send to DWP within 10 days after end of sampling period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference