

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Columbia Agency: REGION 1</th></have<>	County: Columbia Agency: REGION 1	
1			to be half agent for a 1846 (An			minimums been met for this day?	ENTRY POINT	
2								
3	7.3	25.5					EP-A	
4							PWS ID 4100922	
5						VERNONIA, CITY OF		
6							/	
7						Sample period: July / 2024		
8						Month/Year		
9								
10	7.4	25.3	)			Number of excursions during this month:  (Over 9 excursions in 6 months is a violation. Entre Point and Distribution excursions are cumulative).		
11								
12								
13						An 'excursion' is any day in which the water qualit parameter(s) fall below the minimum set by the State.		
14 15								
16								
17	76	21 /						
18	1:0	31.6				Reference		
19			<del> </del>				dinimum Water Quelity	
20						Minimum Water Quality Parameter(s) as set by State:		
21								
22							pH 7.3	
23							Alk 20.0 (Alkalinity)	
24	7.4	<b>Z3.4</b>						
25	, , i							
26								
27						Drint Na	ma: CHPIS PICHAPOSON	
28						Print Name: CHRIS RICHARDSON Signature: 129-6921  Send to DWP within 10 days after end of sampling period		
29								
30								
31								
0 = 1	1 = Ex	cursion	)Tota	I N's		Sampling	y poriod	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/