

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1				V-1	
3 4					
4					
5					,
6	7.4	27.1			V
7					1
8				. 1	
9					
10					
11					
12					
13	7.4	30.0			Y
14					
15					
16					
17					
18					
19					,
20	73	21.7			Y
21					
22					
23					
24					
25					
26					
27	7.3	25.3			V
28					
29	de la constante de la constant		- Control of the Cont	and the second second	
30			- Checkery of the same		
31			and the same of th	and the second	
lo = N	I = Exc	ursion	Total	N's	\$

< <have minimums<="" th=""><th>County: Columbia Agency: REGION 1</th></have>	County: Columbia Agency: REGION 1				
been met for this day?	ENTRY POINT EP-A				
uno day:	PWS ID 4100922				
VERNONIA, CITY OF					
Sample pe					
	Month/Year				

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.3 Alk 20.0 (Alkalinity)
Print Name: Jelf Busch
Signature: 12-3-2H
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/