

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N
1	7.4				Y
2	7.4			-	·V
2 3	7.4				V
4	7.4				V
5	j				
6	)				
.7	7.4				Y
8	7,4				У
9	7.4				Y
10	7,4				У
11	76				7
12					
13	2.				
14	7.4		1		Y
15	7.4				Ý
16	7.6	1			Ý
17	7.5				Y
18	76				Y
19					
20					
21	7.5			5	7
22	7.4				y
23	7.4		TF.		1
24	7.5				1
25	7.5				1
26	7.4				7
27	7.4				1
28	7.6				y
29	7.6				7
30	7.6				7
31	= Excu		-		

< <have< th=""><th>County: Lincoln Agency: REGION 2</th></have<>	County: Lincoln Agency: REGION 2
minimums been met for	ENTRY POINT
this day?	EP-A
	PWS ID 4100925
sw	LINCOLN CO WATER DIST
Sample pe	riod: June 2021
=	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation.

Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum

set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:	
pH 7.1	
	(¥)
Print Name: BARR * ARNOLD	3
Signature: Ram Amol	<del></del>
Date Phone#: 7 - 7 - 21 541-547	-3315
Send to DWP within 10 days after end of sampling period	

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml