

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGION 2</th></have<>	County: Lincoln Agency: REGION 2	
1						minimums	ENTRY POINT	
2						been met for	Service And Manager Andrews	
3						this day?	EP-B	
4							PWS ID 4100925	
5	7.1				У	SW LINCOLN CO WATER DIST		
6							and out to will be be a	
7						Samula na	MAY 2022	
8						Sample period: MAY 2022 Month/Year		
9							Monut real	
10	7.5				Y	Number of ex	cursions during this month:	
11							ions in 6 months is a violation.	
12							d Distribution excursions are	
13						cumulative). A	n 'excursion' is any day in which the	
14							arameter(s) fall below the minimum	
15				-		set by the State	9.	
16	7.5				Y			
17						Referen		
18								
19						1	nimum Water Quality	
	7.5				Y	Pa	rameter(s) as set by State:	
21		\rightarrow			_		pH 7.1	
23			-	-	-	+		
24	-		-				142	
25	\dashv	-	-	-				
26			-	-	-		=	
7	-	-	\dashv	\dashv	\dashv			
28	-	-	-	\dashv	-	Print Name: BARRY ARNOLD Signature: Barry Arnold		
9				-	\dashv			
0			-	\dashv		Date Pho	ne#: 6-8-22: 541-547-33/	
1	-	7	_	-		Send to DWP within 10 days after end of		

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml