

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

D	ay	p	H	All	c F	h	os	Sil	i Y/I
1					T		7		1
2					\dagger		7		1
3		7	7		1		7		1
4					T		7		+
5					+		7		+
6	1				7		7		\top
7					T		T		1
8		7.	9		1		T		Y
9					T		T		
10		70	6		T		T		14
1			1		T		T		1
12	2				T		T		
13	3				T		T		1
14	H				T		T		
15	5		T		T	-	T		
16	T	76	T				T		Y
17			T		T		T		
18	-						T		
19			T				T		
20			T				T		
21	T						T		
22									
23	-	7.6			_				4
24									
25							Γ		
26									
27	b	,4							1/
28									
29	17	8							7
30									
31									
0 =	N =	Ex	cur	sion)	To	ota	IN	's	0

< <have< th=""></have<>
minimums
been met for
this day?

County: Lincoln

Agency: REGION 2

ENTRY POINT

EP-B

PWS ID 4100925

SW LINCOLN CO WATER DIST

Sample period: Twn 2022

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Refe	erence	-
de van een een de bestelle de de de ver	Minimum Water Quality Parameter(s) as set by State	:
to freezo estado do managantado.	pH 7.1	
Print I	Name: BARRI ARNOLT)

Signature: Barry 541-547-3315 Date Phone#: 7-1-22

Send to DWP within 10 days after end of

sampling period

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml