

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	SIII	Y/N
1					
2					
3	Signatural and State of State				
4 1	77				Y
1 2 3 4 5 6	7.5.				Y
6					
-7					
8					
.9	_		-		
	7.5				Y
10 11 12	7.5	-			Y
12					1
13			-		
14					
15					
16					
17	7.6				Y
18	7.7				Y
19					1
20					
21					
22					-
23					
24					
25	-				
26					
27	7.6				Y
28					F
29	percentage and				
30					
31					1

< <have< th=""><th>County: Lincoln Agency: REGION 2</th></have<>	County: Lincoln Agency: REGION 2			
minimums	ENTRY POINT			
been met for this day?	EP-B			
PWS ID 4100925				
SW LINCOLN CO WATER DIST				
Sample	period: JUNE 2025			
	Month/Year			

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Number of excursions during this month: \bigcirc

Referen	Ce —
	inimum Water Quality erameter(s) as set by State:
~ -	pH 7.1
Print Nar	
Signature Date Pho	
	OWP within 10 days after end of

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml