

## Lead & Copper Rule Corrosion Control

		2 4			
Day	рН	Alk	Phos	Sili	Y/N
1	7.4				Y
2	7.5				14
3	7.5				14
4	7.5				14
5	7.5				4
6	7.4				9
7	7.5				4
8	7.5				y
9	7.5				Y
10	7.5	25			Y
11	7,5				14
12	7,5				Y
13	7.5				4
14	7.5				4
15	7,5				4
16	7.5				4.
17	7.6				4
18	7.6				4
19	7.5				4
20	7.5			,	4
21	7.5				4
22	7.5				4
	7.5				Y
24	7.4	23			4
75	7.4				4
26	7.4				4
27	7.3			*	Y
78	7.5				4
70	7,5		1		14
23 24 25 26 27 28 28 29	7.4				Ý
2	117				'
- 1			1		

(No = N = Excursion) Total N's

<>Have minimums been met for this day?

## ENTRY POINT A PWS ID 4100926 WALDPORT, CITY OF

Number of excursions* during this month:
(Count the number of days when any WQP was less than the minimum required)  Total excursions during the previous 5 months:(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative )
Reference
Minimum Water Quality Parameters as set by State:
pH 7.2
Print Name: Lyle T. Arrant  Signature: Jyle I. Grant  Date: 07/08/21  Ind to OHD within 10 days after end of sampling peri

Send to OHD within 10 days after end of sampling period Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381