

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N
1	7.6				У
2	7.5				Y
3	7.6				Y
4	7.6				Y
5	7,5				Y
6	7.5	20			Y
	7,6			1116	Y
8	7.6				4
9	7.4			Manager N. Automorphis Sandwager	Y
16	715				Y
11	7.5				14
12	7,5				Y
13	7.6				14
14	75				Y
15	7.3				Y
16	7,6				Y
17	7.4				Y
18	74				Y
19	7.4	22			Y
20	7,5				Y
21	7.4				Y
22	7.5	_			4
23	75				Y
24	75				Y
25	7.4				1 Y
26	7.5				14
27	7.4				14
28	7.4				14
29	7.4				4
30	7.4				Y
NAME OF TAXABLE PARTY.	m.	1	1		1 1 1

<<Have minimums been met for this day?

ENTRY POINT A PWS ID 4100926 WALDPORT, CITY OF

Sample perio	d: 07/22 Month/Year
	eursions* during this month:
(Count the num than the minim	ber of days when any WQP was less um required)
(Over 9 excursion Point and District Point and District Point and District Point and District Point Po	ns during the previous 5 months: _ _ ons in 6 months is a violation. Entry ibution excursions are cumulative) mpliance? Y/N
Reference	
	linimum Water Quality arameters as set by State:
	pH 7.2
Print Name:_	Lule T. Arrant
Signature:	Les I Whrant

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381

Date: 08/03/22