



Water Quality Parameter Monitoring Form  
**Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Sili	Y/N
1	7.4				Y
2	7.4				Y
3	7.3				Y
4	7.4				Y
5	7.4				Y
6	7.4				Y
7	7.4				Y
8	7.5				Y
9	7.4				Y
10	7.4				Y
11	7.4				Y
12	7.4	24			Y
13	7.4				Y
14	7.4				Y
15	7.5				Y
16	7.4				Y
17	7.5				Y
18	7.5				Y
19	7.4				Y
20	7.4				Y
21	7.5				Y
22	7.4				Y
23	7.3				Y
24	7.4				Y
25	7.5	26			Y
26	7.5				Y
27	7.3				Y
28	7.5				Y

(No = N = Excursion) Total N's ☒

<<Have  
minimums  
been met  
for this day?

**ENTRY POINT**

**A**

**PWS ID 4100926**

**WALDPORT, CITY OF**

Sample period: 02/25  
Month/Year

Number of excursions\* during this month: 0  
(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months  
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative.)  
Is system in compliance? ☒ Y ☐ N

—Reference—

Minimum Water Quality  
Parameters as set by State:

pH



Print Name: Lyle T. Arrant

Signature: Lyle T. Arrant

Date: 03/04/25

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731