

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.56		y	7.73		y
2	7.56		y	7.88		y
3	7.55		y	7.83		y
4	7.51		y	7.64		y
5	7.55		y	7.50		y
6	7.57	31	y	7.53	29	y
7	7.60		y	7.67		y
8	7.62		y	7.74		y
9	7.43		y	7.93		y
10	7.52		y	7.58		y
11	7.56		y	7.32		y
12	7.58		y	7.62		y
13	7.59		y	7.51		y
14	7.56	29	y	7.62	30	y
15	7.57		y	7.66		y
16	7.55		y	7.97		y
17	7.64		y	7.97		y
18	7.51		y	7.47		y
19	7.54		y	7.63		y
20	7.69		y	7.76		y
21	7.74		y	7.73		y
22	7.67	31	y	7.73	27	y
23	7.55		y	7.86		y
24	7.51		y	7.55		y
25	7.44		y	7.54		y
26	7.50		y	7.53		y
27	7.55	31	y	7.62	28	y
28	7.52		y	7.58		y
29	7.53		y	7.65		y
30	7.55		y	7.94		y
31						
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Apr-22

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0


(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R Riggs

**Signature:** 

**Date:** 5/3/2022

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405