

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.43		y	7.59		y
2	7.45		y	7.43		y
3	7.48		y	7.41		y
4	7.46		y	7.60		y
5	7.42	25	y	7.49	26	y
6	7.44		y	7.51		y
7	7.40		y	7.73		y
8	7.40		y	7.70		y
9	7.30		y	7.43		y
10	7.34		y	7.48		y
11	7.62	29	y	7.54	27	y
12	7.57		y	7.50		y
13	7.51		y	7.52		y
14	7.40		y	7.49		y
15	7.44		y	7.50		y
16	7.47		y	7.65		y
17	7.57		y	7.51		y
18	7.57	27	y	7.63	29	y
19	7.54		y	7.52		y
20	7.63		y	7.70		y
21	7.50		y	7.76		y
22	7.61		y	7.72		y
23	7.46		y	7.59		y
24	7.56		y	7.62		y
25	7.52	29	y	7.59	30	y
26	7.47		y	7.68		y
27	7.46		y	7.55		y
28	7.56		y	7.59		y
29	7.51		y	7.43		y
30	7.54		y	7.66		y
31	7.68	35	y	7.78	35	y
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Jan-23

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R. Kress

**Signature:**

**Date:** 2/7/2023

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:

OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405