

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point			Distribution		
	pH	Alk	≥Min? Y/N	pH	Alk	≥Min? Y/N
1	7.36		y	7.40		y
2	7.41	30	y	7.44	31	y
3	7.44		y	7.44		y
4	7.44		y	7.52		y
5	7.42		y	7.50		y
6	7.41		y	7.65		y
7	7.46		y	7.67		y
8	7.41		y	7.45		y
9	7.44	23	y	7.52	29	y
10	7.44		y	7.28		y
11	7.55		y	7.86		y
12	7.54		y	7.67		y
13	7.60		y	7.69		y
14	7.65		y	7.52		y
15	7.65		y	7.62		y
16	7.67		y	7.7		y
17	7.63		y	7.65		y
18	7.40	25	y	7.46	28	y
19	7.49		y	7.5		y
20	7.45		y	7.65		y
21	7.47		y	7.71		y
22	7.30		y	7.55		y
23	7.46	28	y	7.49		y
24	7.55		y	7.55		y
25	7.51		y	7.55	27	y
26	7.41		y	7.61		y
27	7.35		y	7.56		y
28	7.35		y	7.69		y
29	7.32		y	7.4		y
30	7.40		y	7.44		y
31	7.40		y	7.54		y
<b>Total N's</b>			<b>0</b>	<b>0</b>		

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Jan-24

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

Minimum Water Quality Parameters as set by OHA		
	EP	DIST
pH	7.2	7.2
Alk		(Alkalinity)
PO4		(Orthophosphate)
Other		( )

**Print Name:** Justin R. Riggs

**Signature:** *Justin R. Riggs*

**Date:** 2/1/24

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405