

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.66		y	7.67		y
2	7.68		y	7.83		y
3	7.68		y	7.56		y
4	7.74	33	y	7.96	37	y
5	7.80		y	7.85		y
6	7.56		y	8.06		y
7	7.55		y	8.01		y
8	7.57		y	7.70		y
9	7.61		y	7.73		y
10	7.48		y	7.61		y
11	7.47	31	y	7.86	34	y
12	7.55		y	7.58		y
13	7.76		y	7.68		y
14	8.07		y	8.14		y
15	7.74		y	7.87		y
16	7.52		y	7.87		y
17	7.51		y	7.69		y
18	7.56	32	y	7.64	32	y
19	7.56		y	7.66		y
20	7.59		y	7.85		y
21	7.57		y	7.92		y
22	7.62		y	7.75		y
23	7.61	32	y	7.63	32	y
24	7.64		y	7.68		y
25	7.79		y	7.82		y
26	8.10		y	8.17		y
27	8.00		y	7.91		y
28	8.36		y	8		y
29	7.95		y	8.03		y
30	7.79		y	7.98		y
31	7.85	36	y	7.93	37	y
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Dec-25

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk	30	30	(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R Ribbs

**Signature:**

**Date:** 1/5/25

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405