OHA

Water Quality Parameter Monitoring Form

OREGON HEALTH
AUTHORITY

Lead & Copper Rule Corrosion Control

Day	Ph	Alk	Phos	Sili	Y/N	<< Have	
1			1			Minimums	County: Josephine Agency: 5
2	7.5				Υ	Been Met	Entry Point
3					-	for this day	A
4							PWS ID 4100971
5							Cave Junction, City of
6	7.4				Y	1	
7	7.5				Y		Sample Period:
8							Month/Year Jan. 2025
9	7.5				Υ	1 '	
10	7.7				Υ		
11		7,				1	Number of excursions during this month: 0
12						1	
13						7	(Over 9 excursions in 6 months is a violation. Entry
14	7.7				Υ	7	Point and Distribution excursions are cumulative). An
15						7	excursion' is any day in which the water quality
16						7	parameter(s) fall below the minimum set by the State.
17	7.4				Y		
18							
19							
20							Reference
21	7.6				Y]	
22	7.7				Υ		Minimum Water Quality
23							Parameter(s) as set by State:
24	7.4				Υ		
25]	pH 7.3
26							
27	7.5				Υ		
28							0 11 1.
29	7.6				Υ		rint Name: Steven Bethle
30						S	ignature: Sty Botthe
31							Date: 2 - W - 25

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp