

## Lead & Copper Rule Corrosion Control

AUTHORITY

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1	7.5				Y	
2	7.5				Y	
3	7.6				Y	
4	7.4				Y	
5	7.4				Y	
6	7.6				Y	
7	7.6				Y	
8						
9	7.7				Y	Month/Year
10	7.7				Y	
11	7.6				Y	
12	7.6				Y	
13	7.6				Y	
14	7.6				Y	
15	7.6				Y	
16	7.6				Y	
17	7.6				Y	
18	7.7				Y	
19	7.6				Y	
20	7.6				Y	
21	7.7				Y	
22	7.7				Y	
23						
24	7.6				Y	
25	7.4				Y	
26	7.4				Y	
27	7.5				Y	
28	7.5				Y	
29	7.5				Y	
30	7.5				Y	
31	7.5				Y	
No = N = Excursion					Total N's	0

County: Josephine      Agency: 5 <b>Entry Point</b> A PWS ID 4100971 Cave Junction, City of  Sample Period: Month/Year    May 2021
---

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference  <b>Minimum Water Quality Parameter(s) as set by State:</b>  pH <span style="border: 1px solid black; padding: 2px;">7.3</span>
---

Print Name: Steven Bethke  
 Signature: Steven Bethke  
 Date: 6-3-21

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 731-4381    Website: www.ohd.hr.state.or.us/dwp