

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

1	Δ.			(	Y/N	< <have< th=""><th>County: Douglas Agency: REGION 2</th></have<>	County: Douglas Agency: REGION 2	
	POC				POL	minimums	ENTRY POINT	
2	BL	*******			Pol	been met for		
3	POL				POL	this day?	EP-A	
4	8.3			-	V		PWS ID 4101092	
5	POL				POL	USFS TILLER RANGER STATION		
6	POL				POL		,	
7	POL				POL	Sample ne	eriod: 100 22	
3	POL	····			AX	Month/Year		
)	PDL				HOLL			
10	POL				POU	Number of excursions during this month:		
1	POC				POL	(Over 9 excursions in 6 months is a violation.  Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum		
12	POL				POZ			
13	8.4				$\mathcal{A}$			
5	POU	····			POL	set by the State.		
16	Poc				POL	ool by the cla		
17	HOL	·····			P04			
	POL				POL	Refere	nce	
9	POL				POL		dinimum Water Quality	
20	POL				POU		Minimum Water Quality Parameter(s) as set by State:	
21	POL				POZ	•		
22	POL				POC		pH 7.4	
	POL				POL			
24	8.1				Ves			
	POL				POL			
26	POL				POL	_		
27	POL				POL	Print Na	ame: John woody	
28	POL				PDL	Signatu		
29	POL				Por	•	Phone#: 12-8-72 5416436137	
30	8.4				Ves		DWP within 10 days after end of	
34					ι	samplin		
1 = 0	V = Exc	cursion	) Tota	ıl N's	0			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/