

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION :</th></has>	County: Douglas Agency: REGION :
Rs 3	Admin sink	8.4				Y	met the minimum(s)?	DISTRIBUTION
						•	PWS ID 4101092 USFS TILLER RANGER STATION	
								d: <u>March 2021</u> Month/Year lency: Every 6 months
	1						Distribution S	amples required: 1
							Number of exc Sample Period	cursions during this
							(Number of locations when any WQP was less than the minimum.)	
							Excursions are	nt and Distribution cumulative. Add Entry bution Excursions to get period.
							Reference	
								Water Quality ers as set by State:
						1	pH _ 7	.4
	3 3							***
1								1

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/