

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2	
		+					met the	DISTRIBUTION	
Rsz	Treecooler	8.0				1×	minimum(s)?	DISTRIBUTION	
		╂	·				70.77	7C TD 4101000	
	•	 					PWS ID 4101092 USFS TILLER RANGER STATION		
-+		-				<u> </u>			
-						-			
		 					Sample Period: Month/Year Sample Frequency: Every 6 months		
		 				l			
		1		 		 			
	·	1					Distribution Samples required: 1		
	· · · · · · · · · · · · · · · · · · ·	1					Number of excursions during this Sample Period =		
		1				T			
		1							
							was less than the minimum.)		
	-						Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
							•	•	
							Reference	; 0 ————————————————————————————————————	
					,		Minimu	ım Water Quality	
							Parame	eters as set by State:	
							Ha	74	
]	.	
							<u>]</u>		
]	•	
							Deint None	or T How Is bridge	
(N = No = Excursion) Total N's Signature: The Wanty									
	Date: 6-8-21								

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/