

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2	
8-3	Rsz	8.3				7	met the minimum(s)?	DISTRIBUTION	
			-			,	PWS ID 4101092 USFS TILLER RANGER STATION Sample Period: August 202/ Month/Year Sample Frequency: Every 6 months Distribution Samples required: 1		
	1								
							Number of excursions during this Sample Period = Ø (Number of locations when any WQP was less than the minimum.) Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
							Reference		
					,		Paramet	n Water Quality ters as set by State:	
								·	
(N = No = Excursion) Total N's Signature: Signature: 9.9.7.1									

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/