

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Location	pН	Alk	POA	Other	V/N	County: Douglas Agency: REGION 2
-		<del>                                     </del>	Air.			1/13	i met the
RSZ	Tree cooler	7.9				مز	minimum(s)? DISTRIBUTION
		<u> </u>					
							DWG.TD 4101002
	,						PWS ID 4101092 USFS TILLER RANGER STATION
┝					, , , ,		12. 12.
-							Sample Period: November 21 Month/Year
							Sample Frequency: Every 6 months
<del>                                     </del>	1						Distribution Samples required: 1
	· · · · · · · · · · · · · · · · · · ·						Distribution Oamples required.
							Number of excursions during this
							Sample Period = _O_ (Number of locations when any WQP was less than the minimum.)
							Note: Entry Point and Distribution
							Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
	•		1	Ī			• •
	•						Reference
				-	-		
				-+	-+		Minimum Water Quality
							Parameters as set by State:
							pH 7.4
		لــــــــــــــــــــــــــــــــــــــ					
		T					·
	(N = No = Excu	L		stal B	J'a P	14	Print Name: Jonethan Woody Signature: July Woody
	(14 – 140 – EXCL	11 21011	, 10	JIAI F	18	له	Signature: The Charles
							Date: /2-7-Z/

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/