

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID # Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2		
0/6 Toolbarnsink	8.1				Y	met the minimum(s)?	DISTRIBUTION		
		· ·			,	PW	'S ID 4101092		
		USFS TILLE				ER RANGER STATION			
						Sample Frequ	d: October 2027 Month/Year ency: Every 6 months amples required: 1		
						L	of excursions during this		
						(Number of loca	ber of locations when any WQP ess than the minimum.) Entry Point and Distribution sions are cumulative. Add Entry and Distribution Excursions to get or sample period. Reference		
						Excursions are o Point and Distrit			
						Reference			
				,		Minimum Paramete	Water Quality rs as set by State:		
						pH 7.4	4		
(N = No = Excurs	sion)	Tot	al N'	s Q	3	Print Name: _ Signature: _	Trouthan Woody		
						Date: 11-4			

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/