

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Location	pН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2	
12/1	RS 3 Admin sink	8.4				7	met the minimum(s)?	DISTRIBUTION	
			1			,	PWS ID 4101092 USFS TILLER RANGER STATION		
							Sample Period:	Dec 22 Month/Year	
	,						1 1	ncy: Every 6 months mples required: 1	
							Number of excursions during this Sample Period = Ø		
							(Number of locations when any WQP was less than the minimum.)  Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
	<u></u>						Reference -		
					,		Minimum Parameter	Water Quality rs as set by State:	
							pH 7.4	4	
	(N = No = Excursion) Total N's Signature: Jonathan Woody Date: 1-9-7023								

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/