

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

D#	Sample I	_ocation	рН	Alk	P04	Other	Y/N	Has sample County: Douglas Agency: REGION :		
5/2	wash Rock	Hore 876	8.3				Y	met the		
-								minimum(s)? DISTRIBUTION		
								PWS ID 4101092		
1								USFS TILLER RANGER STATION		
							·			
+								Sample Period: <u>May '23</u> <u>Month/Year</u>		
+								Month/Year		
+	·							Sample Frequency: Every 6 months		
+				-				Distribution Samples required: 1		
1						-	\dashv	Number of excursions during this Sample Period =		
-	-							(Number of locations when any MOD		
+								was less than the minimum.)		
+								Note: Entry Point and Distribution Excursions are cumulative. Add Entry		
								Point and Distribution Excursions to get otal for sample period.		
			-		_			Reference -		
-						,	\dashv			
								Minimum Water Quality Parameters as set by State:		
				_				pH 7.4		
							_	P11 7.4		
			-	+-	_		4			
	· · · · · · · · · · · · · · · · · · ·		_	-			\dashv	·		
	(N = No	= Excurs	ion)	Tota	i N's	10	7	Print Name: John Woody		
			,		· • •			Signature: Justin Telanting		
s	end to Drir	nkina Wet	or Dr	^~r~-	~ :4	h : •	.	ys after end of sampling period		

OHA Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/