

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

		}	************************	-	·		•		
ID#	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" td=""><td>County: Douglas Agency: REGION 2</td></has>	County: Douglas Agency: REGION 2	
8-2	tool bain	8,2				Y	met the minimum(s)?	DISTRIBUTION	
			Andrew Control of Control	attança kalanda kirinda	Wokabusaninski kalista				
		*	*****************	and the second s			PW	S ID 4101092	
			-	***************************************			USFS TILL	ER RANGER STATION	
								1 122	
							Sample Perio	d: Aug. '23 Month/Year	
	had had conference on the conference of the conf					***************************************	Sample Frequ	Jency: Every 6 months	
	:			CO-MANAGE AND ASSESSED			Distribution Samples required: 1		
							Number of excursions during this Sample Period = Ø (Number of locations when any WQP was less than the minimum.)		
								•	
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry		
							Point and Distribution Excursions to get total for sample period.		
							-Reference	Q	
					,		Minimu	m Water Quality	
							· ·	ters as set by State:	
							Hq	7.4	
	,								
						±.			
	·								
							Drivé Name	1 1 2 2.	
(N = No = Excursion) Total N's							Jonathan Woody		
Signature: The Lewy Date: 9-5-2023									
	Date:								

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/