

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

7/1	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION</th></has>	County: Douglas Agency: REGION	
2 9	tool bun	8.0			/	7	met the minimum(s)?	DISTRIBUTION	
			-				PW	S ID 4101092	
							1	ER RANGER STATION	
THE STATE OF THE S							Sample Period	d: July '24 / Month/Year	
Control of the Contro							Sample Freque Distribution Sa	ency: Every 6 months amples required: 1	
Software designation of the so		And the second s					Number of exc Sample Period	ursions during this $= \varnothing$	
		- ARTHUR AND PRINCIPLE CALLED AND AND AND AND AND AND AND AND AND AN		The second secon	A CONTRACTOR OF THE CONTRACTOR	7	Number of loca was less than th	tions when any WOP	
The state of the s						$-\mid F$	Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
							Reference		
					, .		Minimum Parameter	Water Quality rs as set by State:	
aliana escriptoriamento de compositorio de la compo	(N = No = Excurs	Zion\	Total				Print Name:	Jonathan Woody	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/