

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location		рН	pH Alk PO4		Other	Y/N	< Has sample	County Douglas Agency REGION 2	
25. ³	Admin sink	6/1/u	8.1				A Account	met the minimum(s)?	DISTRIBUTION	
								USFS TILLE Sample Period	FID 4101092 R RANGER STATION :	
				***************************************	orionesis esercitarios	an-active management of the second		Distribution Samples required: 1 Number of excursions during this Sample Period = (Number of locations when any WQP was less than the minimum.) Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period. Reference Minimum Water Quality Parameters as set by State:		
								pH 7.4		
(N = No = Excursion) Total N's								Print Name: Signature: 7	Tonathan Woody In Clary -10-2027	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/