

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2	
R53	Admin Sink	8,2				7	met the minimum(s)?	DISTRIBUTION	
							PWS ID 4101092 USFS TILLER RANGER STATION		
					·		Sample Period: Seft 7022  Month/Year		
							Sample Frequency: Every 6 months  Distribution Samples required: 1		
							Number of excursions during this Sample Period =  (Number of locations when any WQP was less than the minimum.)  Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
		<del>                                     </del>					Referenc	е ————————————————————————————————————	
					,		Minimu Parame	m Water Quality ters as set by State:	
							pH [	7.4	
	(N = No = Ex	cursio	n) 1	Print Name Signature:	9: Jonathan Woody July Leboury 10-7-22				

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/