

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

[illegible]

(N = No = Excursion) **Total N's**

<Has sample met the minimums?

DISTRIBUTION

PWS ID: 41 0 1 1 2 5

System Name: MTView CO-op A

Sample Period: July 2005
Month/Year

Sample Frequency: weekly

Distribution Samples required: _____

Number of excursions during this Sample Period = _____

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

-For OHA use only

Minimum Water Quality Parameters as set by

pH	7.1	
Alk		(Alkalinity)
PO4		(Orthophosphate)
Other		()

Print Name: Ricky White

Signature: R. J. White

Date: Aug 7 7025

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>