

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	Sample Location (Other than Entry Point)	pН	Alk	PO4	other	Y/N
13		7.4				Y
27		7.3				Y
	(N = No = Excur	reion)		     tal N's	 _	0
		51011)			3	

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

	se only Water Quality ers as set by
pH 7.2 Alk PO4 Other	(Alkalinity) (Orthophosphate)
Print Name: Signature:	Jeffrey Olson
Date: 0 <u>4/09/2</u>	<u>2024</u>

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/