

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Location	рН	Alk	P04	other	Y/N	<has p="" sample<=""></has>
			7011				met the DISTRIBUTION
							PWS ID: 41 0 1 2 3 3
$\dashv$							System Name: Dear Island Waterwork
							Sample Period: December 21  Month/Year
							Sample Frequency:
0							Distribution Samples required:
3	HOSE Bib	7.3				Y	Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
							Note: Entry Point and Distribution
							Excursions are cumulative. Add Entry Point and Distribution Excursions to get
							total for sample period.
							For OHA use only
							Minimum Water Quality Parameters as set by
77	Ilas Ris	7,3				4	pH 📜
61	HU3E 13 3	(,)					Alk (Alkalinity)
				1	1		PO4 (Orthophosphate)
							Other
							Print Name: Jakh Menn
	/h) h)	<u> </u>	\ _	1	<u></u>		Signature:
(N = No = Excursion) Total N's						U	Date: 12/27/21

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/