

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

D#	Sample Location	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>
ĺ							met the DISTRIBUTION minimums?
2		-					PWS ID: 41 0 1 2 3 3
3		+					System Name: Deer Island Warter Works
6		1					Sample Period: July Zozi Month/Year
8							Sample Frequency:
10					· ·		Distribution Samples required:
11	Hose B15	7.2				V	Number of excursions during this
13							Sample Period =
14							(Number of locations when any WQP was less than the minimum.)
15							, in the second
16							Note: Entry Point and Distribution Excursions are cumulative. Add Entry
17							Point and Distribution Excursions to get
18							total for sample period.
19		1					For OHA use only
20							
24							Minimum Water Quality
26	Hose Bib	7.3				Y	Parameters as set by
28							pH
29							Alk (Alkalinity) PO4 (Orthophosphate)
30							Other (Ontriophosphate)
31							
							Print Name: Justin McMuller
	/h	<u> </u>				_	Print Name: Justin McMullen Signature: Just Manua
(N = No = Excursion) Total N's							Date: <u>8/8/2/</u>

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/