

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

	Day	/ pH	Alk	Phos	Other	YIN
	1	7.5				
	.2	7.8				
	3	7.4				
	4	7,7				
	5	9.0				
	6			877		
	7	7.7				
	8	7.6				
	9	7.7				
	10	7.9				
	11	7.8				4
	12	7.7		·		
	13	7,6				
	14	7,9				
	15	7.6				
	16	7.7				
ļ	17	7,7				508 Y
	18	7.8				
	19	8.0				
	20	7.6				
	21	7.9				
	22	7.7				
-	23	9,0				_
-	24	7.8				
-	25	7.9				_
-	26	8.0	-			_
ŀ	27	7, 9				$\dashv$
-	28	7.6				_
-	29	7.5				
-	30	7,9				_
L	31					
(N	o = N	= Excu	irsion)	Total l	N's (	$\supset$

< <have< th=""><th>County: Multnomah Agency: MULTNOMAH COUNT</th><th>TY</th></have<>	County: Multnomah Agency: MULTNOMAH COUNT	TY
minimums	ENTRY POINT	•
been met for this day?	EP-A	
ans day!		
3	PWS ID 4101267	
17	MANNA HOUSE CHURCH	
Sample pe	priod: 09/24	
-	Month/Year	
Number of ev	cursions during this month:	
	sions in 6 months is a violation.	
Entry Point an	d Distribution excursions are	
annondadi \		
cumulative). A	An 'excursion' is any day in which t	he
water quality p	An 'excursion' is any day in which to arameter(s) fall below the minimur	he n
cumulative). A water quality p set by the Stat	An 'excursion' is any day in which to arameter(s) fall below the minimur	he 'n
water quality p	An 'excursion' is any day in which to arameter(s) fall below the minimur	he n
water quality p set by the Stat	An 'excursion' is any day in which to parameter(s) fall below the minimur te.	he n
water quality p	An 'excursion' is any day in which to parameter(s) fall below the minimur te.	he n
water quality p set by the Stat	An 'excursion' is any day in which to parameter(s) fall below the minimur te.	he n
water quality p set by the Stat	An 'excursion' is any day in which the parameter(s) fall below the minimumes.	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum te.  Ince  Inimum Water Quality arameter(s) as set by State:	he n
water quality p set by the Stat	An 'excursion' is any day in which to arameter(s) fall below the minimum te.  Ince	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum te.  Ince  Inimum Water Quality arameter(s) as set by State:	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum te.  Ince  Inimum Water Quality arameter(s) as set by State:	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum te.  Ince  Inimum Water Quality arameter(s) as set by State:	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum te.  Ince  Inimum Water Quality arameter(s) as set by State:	he n
water quality p set by the Stat	An 'excursion' is any day in which the arameter(s) fall below the minimum in the common in the commo	he n
water quality p set by the Stat  Referen  M P:	An 'excursion' is any day in which the arameter(s) fall below the minimum fe.  Ince  Inimum Water Quality arameter(s) as set by State:  pH 7.2	he m
Print Nar Signature	An 'excursion' is any day in which the arameter(s) fall below the minimum in the common in the commo	<i>-</i>

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period