

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County</th><th>r: Clackamas Agency: Clack</th></have<>		County	r: Clackamas Agency: Clack		
W.	ell #1				y	1000	mums n met for	EN	TRY POINT		
16	7.2				y		day?	EP-A	EP-A		
1/8	7.3		Feh to	Wel	1#2	7		DWG	ID 4105086		
413	7.7	30			30						
4/18	7.4				y	POLEHN HEIGHTS WATER ASSN.					
1/24	7,5				4						
学							Sample period: <u>JANUARY 2021</u>				
+									Month/Year		
					Number of excursions during this month:						
						(Over 9 excursions in 6 months is a violation. Entry					
						Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.					
					-	Reference					
<u> </u>						1		Minimur	n Water Quality		
			<u> </u>		-		Parameter(s) as set by State:				
	7						pH 72				
				TI.			pH 7.2				
						7					
								4/2000			
							Drint Name: St. 1/2 )-1/				
					-	Print Name: Sheila H. Wahl Signature: Sheila H. Wahl					
			-		-	Date: 4 Feb 2021					
<u></u>			<u> </u>			4					
No =	No = N = Excursion) <b>Total N's</b> Send to DWP within 10 days after end of										
sampling period											

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp