

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					1
2 3					
4	8.0				il
5					Ŷ
6		-			
7	7.8	35	-		y
8					0
9					
10	8.0				4
11					0
12					
13	9.0	t:			y
14			_		0
15		,			E.
16	8.8/	a			y
17	/ "				0
	7.4				y
19					0
20	-				
21		- R.			
22	7.3	-			4
23					0
24		-			
25	7.3				4
26					0
27					
28	7.2	25			4
29					0
30					
31					
o = N	= Exc	ursion)	Total	N's	Ø

< <have minimums</have 	County: Clackamas Agency: CLACKAMAS COUNTY				
been met for this day?	EP-A				
	PWS ID 4105086				
POL	EHN HEIGHTS WATER ASSN				
	Well # 1				
Sample period: <u>June</u> 2033					
	Month/Year				

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference	
Minimum Water Quality Parameter(s) as set by State:	
pH 7.2 Alk 25.0 (Alkalinity)	
Print Name: <u>Sheila</u> <u>H. Wahl</u> Signature: <u>Keela</u> <u>H. Wahl</u> Date & Phone#: <u>10 July 2023</u> 971-998-	6481

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/