

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <hav< th=""><th>.0</th><th>County Marion</th></hav<>	.0	County Marion		
	1]	-		minimu	_	County: Marion Agency: MARION COUNTY		
	2	<u> </u>	<u> </u>				been n	1	ENTRY POINT		
	3	 					this da		EP-A		
	4								PWS ID 4190587		
	5							S	SILVER CREST SCHOOL		
4	6	8.33	140								
	7					7.7	Sample period: \antiemathan 2025				
	8						Month/Year				
	9						IVIOIILII/ TEAM				
	10						Num	ber of ex	cursions during this month:		
4	11						(Over 9 excursions in 6 months is a violation.				
	12						Entry Point and Distribution excursions are				
	13						cumulative). An 'excursion' is any day in which the				
	14	7.48	129				water quality parameter(s) fall below the minimum set by the State.				
	15										
	16						_Reference				
	17										
	18										
	19							M	linimum Water Quality		
	20						Parameter(s) as set by State:				
	21								nH 72		
	22							P	pi		
		8.3%	131								
	24										
	25										
	26										
	27						Print Name: Left Frally Now				
	28						Signature: Signature:				
	29						Date & Phone#:				
	30					_					
	31	8.78	135					Send to L sampling	DWP within 10 days after end of		
(N	lo = N	l = Excı	ursion)	Total	N's			samping	Period		
		~			느						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/