

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

j	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Marion</th><th>Agency: MARION COUNTY</th></have<>		County: Marion	Agency: MARION COUNTY	
	1						minimu		ENTRY	POINT	
A	-2	7.84	149				been m				
	3						this day	<b>'</b> ?	EP	-A	
	4						PWS ID 4190587 SILVER CREST SCHOOL				
	5	·									
¥	6										
	7						Sample period: MAY 7025  Month/Year				
	8										
	9	<u>753                                    </u>	131	ļ <u> </u>							
	10			<u> </u>			Number of excursions during this month:				
*	11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are				
	12	· ·									
	13		1 7 7	ļ			cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.				
		7:76	133	-							
	15	<del> </del>					sor by the state.				
	16			<u> </u>							
*	17						Reference				
	18			<u> </u>					85	0	
	19 20	707	170					Minimum Water Quality Parameter(s) as set by State:			
	21	7.87	128	<del> </del>		—		· ·	arameter(s)	as set by otate.	
	22	·							pH 7.2		
	23			<del> </del>							
	24			<del> </del>							
4	25		<u> </u>								
	26							Print Name: Jeff Alderman			
	27			<u> </u>							
	28					$\neg$					
		7.43	1110					Signatu	1 1001	1.901-1522 522	
	30		TITA.	<u> </u>					Phone#:	5-99170572 5-29-21	
	31						Send to DWP within 10 days after end of				
$t^{\prime}$	No = N = Excursion) <b>Total N's</b>							sampling	g perioa		
1,	. 10			-/ I OLG							

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/