

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

i i	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th><u> </u></th><th>County: Marion</th><th>Agency: MARION COUNTY</th></have<>	<u> </u>	County: Marion	Agency: MARION COUNTY	
	1	8,14	104				minimu	;	ENTRY		
-7V -	2	9					been m				
	3						this day	'?	EP	-A	
	4								PWS ID 4	190587	
	5						SILVER CREST SCHO			ST SCHOOL	
	6						Sample period: Lux 2025				
	7										
X	-8	F0,K	إليلو				Month/Year				
F	9										
	10						Number of excursions during this month:				
	11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.				
	12										
¥	13										
	14										
	15	7.29	137								
	16			<u> </u>							
:	17						[Refere	nce ———		
	18										
	19								/linimum Wat	_	
*	20			ļ				ŀ	arameter(s)	as set by State:	
	21	4 8 7	25.4.4						pH 7.2		
		7.87	144						- <u>I</u>		
	23										
	24				<u> </u>						
	25	ļ									
*	26			<u> </u>	1						
	27		1	<u> </u>	<u> </u>			Print Na	ame:	Plannan	
	28	-7 01	1,5	<u> </u>		-		Signatu		KILL	
	29	7,90	115/	 	-			Date &	Phone#: <u>│ </u>	255 93-091-657	
	30	 			<u> </u>			Send to	DWP within 1	0 days after end of	
	31		<u> </u>	<u> </u>	<u> </u>				g period		
((No = N = Excursion) Total N's										

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/