

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	рН	Alk	Phos	Other	Y/N
1					
3	6.7		1.0		Y
4					
5	67		1.0		Y
6					
7					
8					
9					
10	6.7		1.0		Y
11					
12					
13	6.7		1.0		Y
14					
15					
16	6.7		1.0		4
17					
18		_			
19	6.8		1.0		Y
20					
21 22					
22					
23	6.7		1.0		7
24					
25					
	6.7		1.0		Y
27				^	
28					
29					
30					
31	6.7		Total		Y

< <have< th=""><th>County: Linn Agency: LINN COUNTY</th></have<>	County: Linn Agency: LINN COUNTY
minimums been met for	ENTRY POINT
this day?	EP-A
	PWS ID 4191671
DIX	XIE ELEMENTARY SD 509J
Sample pe	riod: May 2012 Month/Year

Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are

cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum

set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 6.7
PO4 1. (Orthophosphate)
Print Name: M4H Holl: day Signature: MMM / J.
Date & Phone#: 6/8/2022 541-602-2943
Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period