

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services						įv .		
Day	рН	Alk	Phos	Sili	Y/N	<- <have< th=""><th>County: Linn Agency: Linn</th></have<>	County: Linn Agency: Linn	
$u/_{\chi}$	7.4					minimums been met for	ENTRY POINT	
11/2	7.4					this day?	EP-A	
11/3	7.3				ļ		PWS ID 4191707	
11/4	<u> </u>				ļ			
11/5	3.4				<u> </u>	PLI	EASANT VALLEY ELEM SD #55	
11/8	4.3						.00001	
1/0	4.9			-		Sample period: 10vem ber 202		
1710 11 / N	1.2		ļ		ļ		Month/Year	
11/1)	7				<u> </u>	<u> </u>		
<u>"//2</u>	4.5					Number of	excursions during this month:	
17.15	72	<u>-</u>	<u> </u>		<u> </u>	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
11/10	4.3							
11/19	$\frac{7}{2}$	<u> </u>						
11/10	7.2	-			<u> </u>			
1/22	7.3					State.	,	
11/27	7.3	,						
11/29	7.4					⊢Refe	rence	
11/30	7.3							
							Minimum Water Quality	
			<u> </u>	<u> </u>			Parameter(s) as set by State:	
			<u> </u>		<u> </u>		pH 7.2	
					ļ		' -	
							ļ	
			ļ		1			
			ļ		ļ			
	<u> </u>	<u> </u>	<u> </u>					
			1			Print Nam	ne: Loni Weinman	
 -		 		 	-	Print Name: Loni Weinman Signature: Jon M W		
ļ	┼		╁┈	-		Date: 12	-3-202)	
└── Va =	I N = Fy	CUESIO	n) Tot a	ıl N'e		-	WP within 10 days after end of	
		J. (J. ()	·/ \\	3	\mathcal{L}	sampling r	**	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp