

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

oregon department of human services								
Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Linn Agency: Linn</th></have<>	County: Linn Agency: Linn	
12/2	73					minimums	ENTRY POINT	
12/3	7.4					been met for this day?	EP-A	
12/6	2.3					uns day:		
12/7	7.3			* -			PWS ID 4191707	
12/8	7.4					PLEASANT VALLEY ELEM SD #55		
12/9	7.3							
12/10	7.4				ļ	Sample period: <u>December 202</u> Month/Year		
12/13	7.3							
14	7				 	-		
10/15	7.3					Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
2/0	7.4		 		 			
71]	7,7				 			
			<u> </u>		 			
1								
							2001 0 1 10 2022	
						Reference emailed 1-4-2022		
	<u> </u>				<u> </u>			
		<u> </u>	<u> </u>		<u> </u>		Minimum Water Quality	
		 -	 	 	_		Parameter(s) as set by State:	
						-	pH 7.2	
<u> </u>			 	<u> </u>	 			
<u> </u>		 	-		+	1		
-	 	_	 	-	+	1		
-	 	╁──	 		-			
			 	<u> </u>	1		1 1 1	
	 	1				Print Nar	ne: Loni Weinman	
	 	<u> </u>	†	1	1	Print Name: Loni Weinman Signature: Jon Mhi		
		1				Date: <u> -</u>	4-2022	
- OV:	No = N = Excursion) Total N's Send to DWP within 10 days after end of							
	sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp