

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

<u> </u>	of numan services					* 1 -1,	1	
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
6/1	7.4					minimums	ENTRY POINT	
6/2	7.4					been met for this day?	EP-A	
6/3	5. 7.					Linis day :		
6/6	7.3						PWS ID 4191707	
6/7	7.4					PL	EASANT VALLEY ELEM SD #55	
6/8	7.4							
6/q	7.3					Sample	period: June 2022	
6/10	7.4					Campic	Month/Year	
6/13	7.2							
6/14	7.3				ļ			
6/15	7.2		ļ <u>.</u>		<u> </u>	Number of	excursions during this month:	
6/16	<u> 7.3</u>					(Over 9 exc	eursions in 6 months is a violation. Entry	
6/17							istribution excursions are cumulative).	
6/20	>	. <u></u>				1	on' is any day in which the water quality	
6/21		<u> </u>			<u> </u>		s) fall below the minimum set by the	
6/22	7.5	<u> </u>			<u> </u>	State.	•	
6/23	7.4	<u> </u>			<u> </u>		amailad 2/5/2000	
0/24	7.4				<u> </u>	Refe	erence emailed 7/5/2022	
927	2.5				<u> </u>		·	
6/28	7.4		ļ		<u> </u>		Minimum Water Quality	
6/29			<u> </u>		 		Parameter(s) as set by State:	
9/30	<u> </u>				 -		pH 7.2	
			<u> </u>	 	}	-		
		<u> </u>	<u> </u>	 	<u> </u>	-		
	<u> </u>		<u> </u>	<u> </u>	<u> </u>			
			ļ	<u> </u>	-			
		ļ	<u> </u>		-			
<u> </u>		ļ		-	-	Print Name: 1 pri 12 Jeinman		
				<u> </u>	-	Print Name: Loni Weinman Signature: Son ni Wi		
-		_	-	Date: 7-8-2022				
No - N - Evoursion Total NII-								
No = N = Excursion) Total N's						Send to DWP within 10 days after end of		

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp

sampling period