

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	of human services							
Day	рН	Alk	Phos	Sili	Y/N	<' <have< td=""><td>County: Linn Agency: Linn</td></have<>	County: Linn Agency: Linn	
11/2	75					minimums	ENTRY POINT	
117	75					been met for		
116	77					this day?	EP-A	
11/7	7.6						PWS ID 4191707	
NX	75			_		PL	EASANT VALLEY ELEM SD #55	
11/11	7.8							
Ule	ラヴ					Sample period: Month/Year		
11/16	78							
1112r	2.60						Workin rear	
11/21	ブラ							
1/29	7.5					Number of excursions during this month:		
1/30	7.5	<u> </u>				(Over 9 excursions in 6 months is a violation. Entry		
						Point and Distribution excursions are cumulative).		
		<u>.</u>	<u> </u>			An 'excursion' is any day in which the water quality		
						parameter(s) fall below the minimum set by the		
					<u> </u>	State.		
				ļ. .			erence emailed 12/5/23	
· · · · · · · · · · · · · · · · · · ·	}	-	-		-	Refe	erence	
-	<u> </u>	 	 				Minimum Water Quality	
	 			 			Parameter(s) as set by State:	
		 	 		╁			
 		 	 		 	-	pH 7.2	
-		-	-	 		1		
		╁──	-	 	 			
		 	-		 	-		
		 	├		-	-		
	<u> </u>	-	<u></u>	<u> </u>		ł L		
	-		+	 		Print Nar	ne: Lon Wanman	
	 	 -	 		-	Signature: Am M		
-	 	┼	 	 	1-	Date: \2	F 7	
L	<u> </u>	l voursis	n\T-4-					
140 =	No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period							
sampling period								