

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

of human services						år		
Day	рН	Alk	Phos	Sili	Y/N	<-Have	County: Linn Agency: Linn	
1/2	7.4	<u> </u>				minimums	ENTRY POINT	
1/3	71			<u>.                                    </u>		been met for		
1/U	51					this day?	EP-A	
1/5	7.2						PWS ID 4191707	
118	7.5					PL	EASANT VALLEY ELEM SD #55	
1/0	7.4							
1/11	7.6					Sample	period: January 2024	
417	7.8					Month/Year		
1/19	7.5							
1/22	7.4							
1/23	7.3					Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
424	7.4							
1/26	7.4							
1/29	7.4							
1/30	7.4							
1/31	7.5					State.		
							erence emailed 2-5-2024	
						Refe	erence Chillen a Savar	
							Minimum Water Quality	
							Parameter(s) as set by State:	
	-	<u></u>			<del>                                     </del>			
				<del></del>	<del> </del>		pH 7.2	
-								
ļ					<del>                                     </del>			
					1	·		
-								
						Print Nam	ne: Loni Weinman	
						Signature	: Lon mhi	
					<del> </del>	Date: 2	-5-2024	
No = 1	No = N = Excursion) <b>Total N's</b> Send to DWP within 10 days after end of							
	sampling period							
						. 51		

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp